

SPECTRA PREMIUM HAS YOU COVERED FOR THE JOB

PART# 7-4283

Parallel flow condensers are susceptible to severe internal blockage after a compressor failure. When the compressor fails, always include a Spectra Premium condenser to ensure complete repair.



AVAILABLE NOW

SPECTRA PN	OE PN	APPLICATIONS
 <p>7-4283</p>	23141861	18-15 Cadillac Escalade; 18-15 Cadillac Escalade ESV; 15-14 Chevrolet Cheyenne; 18-16 Chevrolet Cheyenne; 18-14 Chevrolet Silverado 1500; 15-14 Chevrolet Silverado 2500; 17 Chevrolet Silverado 2500; 16 Chevrolet Silverado 2500

SPECTRA
PREMIUM™

TRUST PARTS
developed and engineered here